



ADAS Find LLC.
 4595 Broadmoor Ave SE Ste 110
 Grand Rapids, MI 49512
 (517) 883-2217

Date: 06-17-2026
Retail Price: \$12 plus taxes
Shop: service@adasfind.com
Technician: John Smith

ADAS & Safety Requirement Report

Vehicle: 2024 LEXUS ES

VIN: 1XXXXXXXXXXXXXXXXX

Insurance: SELF PAY

RO: 12345

Equipped ADAS Features:

- Millimeter Wave Radar
- Forward Recognition Camera
- Blind Spot Monitor Sensor
- BackUp Camera
- Front Ultrasonic Sensors
- Rear Ultrasonic Sensors
- Surround View Cameras
- Steering Angle Sensor

ADAS Calibrations: 3

• Millimeter Wave Radar

Line Caught: 5 Repl Bumper cover w/park alert US 521190X948 1 467.42 Incl. 3.0

Requirement: front bumper is damaged or deformed due to an accident

OEM Reference: [ADAS Calibration Requirement Link \(Requires TIS Access\)](#)

Alternative Reference: [ADAS Calibration Requirement Link \(Requires ALLDATA Subscription\)](#)

Procedure: [ADAS Calibration Procedure Link \(Requires ALLDATA Subscription\)](#)

Calibration Type: STATIC

Calibrate With Bumper: ON

• Front Ultrasonic Sensors

Line Caught: 15 Repl Grille assy w/o F sport, w/hybrid 5310106320 1 815.47 0.4

Requirement: When the radiator grille and ultrasonic sensor is damaged or deformed due to an accident or contact with other objects

OEM Reference: [ADAS Calibration Requirement Link \(Requires TIS Access\)](#)

Alternative Reference: [ADAS Calibration Requirement Link \(Requires ALLDATA Subscription\)](#)

Procedure: [ADAS Calibration Procedure Link \(Requires ALLDATA Subscription\)](#)

Calibration Type: STATIC

• Surround View Cameras

Line Caught: 8 Add for front camera m 0.2 M

Requirement: Replacement or removal and installation of the television camera

OEM Reference: [ADAS Calibration Requirement Link \(Requires TIS Access\)](#)

Alternative Reference: [ADAS Calibration Requirement Link \(Requires ALLDATA Subscription\)](#)

Procedure: [ADAS Calibration Procedure Link \(Requires ALLDATA Subscription\)](#)

Calibration Type: STATIC

Disclaimer: This report is for informational purposes and does not substitute for professional advice. ADAS features, sensor configurations, and procedures may vary depending on your vehicle's specifications. You are responsible for verifying details and providing feedback. Always refer to your owner's manual for precise information. We are not liable for any inaccuracies, omissions, or actions taken based on this report. © ADAS Find. All rights reserved. All other product and company names are trademarks or registered marks of their respective holders. Use of them does not imply any affiliation with or endorsement by them.



Safety Actions: 5

- **OEM Pre-Scan**
Requirement: After ANY collision occurs
OEM Reference: [Pre- & Post-Scan Position Statement](#)
- **OEM Post-Scan**
Requirement: After ANY collision occurs
OEM Reference: [Pre- & Post-Scan Position Statement](#)
- **Occupancy Detection System Rezeroing**
Requirement: After ANY collision occurs
OEM Reference: [ADAS Safety Action Link](#)
- **Seat Belt System Check**
Requirement: After ANY collision occurs
OEM Reference: [ADAS Safety Action Link](#)
- **SRS Check**
Requirement: After ANY collision occurs
OEM Reference: [ADAS Safety Action Link](#)

Programming / Initialization Actions: 1

- **Adaptive Headlamp**
Line Caught: 20 Rep! RT Headlamp 8114533L80 1 2,945.26 0.4
Initialization Requirement: when the headlight swivel ECU is replaced.
OEM Reference: [Initialization Requirement Link \(Requires TIS Access\)](#)
Alternative Reference: [Initialization Requirement Link \(Requires ALLDATA Subscription\)](#)
Procedure: [Initialization Procedure Link \(Requires ALLDATA Subscription\)](#)
Calibration Type: INITIALIZE